




Linac to S1 to FFA first pass with 4th order PTC, 10 slices




Linac to S1 to FFA first pass with 1th order




FFA first pass with 4th order PTC, 10 slices




FFA first pass with 1th order




R1 to Linac first pass with 4th order PTC, 10 slices




R1 to Linac first pass with 1th order





S2 to FFA second pass with 4th order PTC, 10 slices




S2 to FFA second pass with 1th order




FFA the second pass with 4th order PTC, 10 slices




FFA the second pass with 1th order




FFA to R2 the second pass with 4th order PTC, 10 slices



FFA to R2 the second pass with 1th order



S2 to FFA the third pass with 4th order PTC, 10 slices



S2 to FFA the third pass with 1th order

