

# CBPM waveform time skipping

Antoine, Will, Laurel, Mike

CESR instrumentation meeting – Feb 14<sup>th</sup>, 2025

# Waveform time skipping


Studies on the bench made possible by new setup and new DSP firmware, CBIC software. Collected waveform data averaging up to 200 turns with ctacf122:

- used timing card, see [instr. elog 2411](#)
  - 4 channels all together: about 12 kADC counts
  - 1 channel at the time: about 30 kADC counts
- brand new card, see [instr. elog 2414](#):
  - 1 channel at a time: about 30 kADC counts


**Caveat:** cannot align the waveforms with bench setup (timeout issue)

Used timing card


# 4 channels: 1-turn average




# 4 channels: 100-turn average




# 4 channels: 200-turn average




# 4 channels: 200-turn average




# 4 channels: 200-turn average




# 4 channels: 200-turn average




# 1 channel: 200-turn average




# 1 channel: 200-turn average



# 1 channel: 200-turn average




# 1 channel: 200-turn average




Brand new timing card


# 1 channel: 200-turn average




# 1 channel: 200-turn average



# 1 channel: 200-turn average



# 1 channel: 200-turn average



# Takeaway

Brand new timing card exhibits non-uniform time stepping

Next step: collect zero-crossing data on the bench → jitter measurement

- requires being able to align the waveform

# Extras